

Merchant & Gould

An Intellectual Property Law Firm

Merchant & Gould P.C.
701 Fifth Avenue
Suite 4700
Seattle, WA 98104-7097

A Professional Corporation

Fax Transmission | December 19, 2005

TO:

ATTN MICHELLE WILLIAMS Certificate of Corrections Branch Commissioner for Patents P.O. Box 1450 Alexandria, Virginia 22313-1450	FROM: Alice Baum OUR REF: 50019.51US01; 50019.56USU1; 50019.57USU1 TELEPHONE: 206-342-6246
---	---

Total pages, including cover letter: 5PTO FAX NUMBER 1-703-746-4661

If you do NOT receive all of the pages, please telephone us at 206.342.6200, or fax us at 206.342.6201.

Documents Transmitted:

Certificates of Correction

Patent Nos.

~~6,631,066 B1~~~~6,768,355 B1~~

6,775,112 B1

09/849707

**Please issue new certificate with correct patents as shown by the attached.
Thank you.***Give to Tony*

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,775,112 B1

DATED : ~~November 12, 2004~~*August 10, 2004*

Page 1 of 2

INVENTOR(S) : Gregory J. Smith et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title page.

Item [57], ABSTRACT, "and cause the active device to 'turn on'" should read -- and cause the active device to "turn on." --

Column 7.

Line 20, "SO as to" should read -- so as to --

Column 8.

Line 6, "1.8. k Ω ." should read -- 1.8 k Ω . --

Line 23, "a GaAs, FET to JFET" should read -- a GaAs, FET JFET --

Column 10.

Line 31, "inverter 160" should read -- inverter I₆₀ --

Line 38, "at node N₆" should read -- at node N₆₁ --

Column 11.

Line 59, "ground terminal response to" should read -- ground terminal in response to --

Line 66, "the protection circuit fry" should read -- the protection circuit further --

Column 12.

Line 2, "the signal firm the power" should read -- the signal from the power --

Line 15, "slower than the fist" should read -- slower than the first --

Column 13.

Line 6, "transient evens" should read -- transient events --.

Line 56, "a slow ESD event an the power" should read -- a slow ESD event on the power --